What is it?

This document contains corrections to the CLJ9500/CLJ9500mfp Combined Engine service manual. It is a living document and will be updated as the need for corrected information is found.

Corrections

Page 94

Please correct the steps to read as follows:

Reinitialize a hard disk using the control panel

- 1 Turn the printer (MFP) off.
- **2** Turn the printer (MFP) on.
- **3** Press and hold PAUSE/RESUME (LJ 9500) or Left side of the START button (LJ 9500mfp) on the control panel during the memory count.
- **4** Hold PAUSE/RESUME (LJ 9500) or Left side of the START button (LJ 9500mfp) down until all three error lights illuminate steadily.
- **5** Press until INITIALIZE DISKS appears on the display panel (for the MFP press the 5 button approximately 5 seconds and release to see INITIALIZE DISKS.)
- 6 Press (the 6 button on the MFP).
- **7** The printer begins initializing the disk (this might take a moment). The control panel displays the HP event logo and eventually displays READY.

Page 289

Add to the registration assembly re-install instructions:

• Ensure the registration assembly plate is installed with guides under the holding tabs and that it sits level in the engine.

Page 337

Correct the sensors option listing for J to "Duplex Feed".

Page 456

59 error messages in the service manual are listed by Front Panel display only. The following event log messages correlate as follows:

| Event log message | Front panel message(s) | Event |
|-------------------|------------------------|-----------------------------------|
| 59.01.00 | 59.10 | Motor Startup Error |
| 59.02.00 | 59.20 | Motor Rotation Error |
| 59.03.00 | 59.30 | Fuser Motor Startup Error |
| 59.04.00 | 59.40 | Fuser Motor Rotation Error |
| 59.05.00 | 59.5K | K Image drum Motor startup error |
| | 59.5C | C Image drum motor startup error |
| | 59.5M | M image drum motor startup error |
| | 59.5Y | Y Image drum motor startup error |
| 59.06.00 | 59.6K | K Image drum motor rotation error |
| | 59.6C | C Image drum motor rotation error |
| | 59.6M | M Image drum motor rotation error |
| | 59.6Y | Y Image drum motor rotation error |
| | 59.7C | C Developer Motor startup error |
| 59.07.00 | 59.7M | M Developer Motor startup error |
| | 59.7Y | Y Developer Motor startup error |
| | 59.8K | K Developer Motor rotation error |
| 59.08.00 | 59.8C | C Developer Motor rotation error |
| | 59.8M | M Developer Motor rotation error |
| | 59.8Y | Y Developer Motor rotation error |

| <u>59.09.00</u> | 59.90 | ITB Motor rotation error |
|-----------------|-------|-----------------------------------|
| | | |
| 59.99.00 | 59.99 | T2 clutch error |
| | | |
| 59.10.00 | 59.A0 | ITB Motor rotation error |
| | | - |
| 59.13.00 | 59.D0 | Registration Motor starting error |
| | | |
| 59.14.00 | 59.E0 | Registration Motor rotation error |

Page 543

Correct 'crg driver PCB assembly (print cartridge drive)' to have the following part number:

RG5-5907-020CN

Correct 'DC Controller PCB Assembly' to have the following part numbers:

- RG5-5901-060CN (9500)
- RG5-5976-030CN (9500MFP)

HP LJ9000mfp; LJ9000Lmfp; LJ9040mfp; LJ9050mfp

Version 2.0

Table 1. Consumables, supplies, accessories, FRUs, and documentation (continued)

| Product number | Service number | Exchange | Description | Printer |
|----------------|----------------|----------|-------------|---------|
| | | number | | |
| Consumables | | | | |

| C8543X | | C8519-69009 | Print cartridge | |
|----------------|--|---------------|--|--------------------------------------|
| 000 10/1 | C8085-60541 | 20010 00000 | Staple cartridge (3,000-sheet | |
| | | | stapler/stacker) | |
| | C8088-60541 | | Staple cartridge (multifunction finisher) | |
| Supplies | • | • | · · · · · · · · · · · · · · · · · · · | |
| C9152A | C9152-67904 | C9152-69004 | PM kit/110 V | |
| C9153A | C9153-67904 | C9153-69004 | PM kit/220 V | |
| Parts | | | | |
| | C8523-67902 | | Formatter assembly | HP LJ 9000mfp |
| | Q2622-67901 | | Formatter Assembly | HP LJ 9000Lmfp |
| | Q3726-67905 | | Formatter assembly (Note: Do not replace the formatter and the CompactFlash firmware at the same time) | HPLaserJet 9040mfp and 9050mfp |
| | C9147-67926 | | Firmware Dimm | LJ9000mfp and LJ 9000Lmfp |
| | Q2635-67903 | | Firmware Compact Flash | LJ9040mfp and LJ9050mfp |
| | C9168-67906 | | Copy Processor Firmware 8MB | LJ9000mfp and |
| | C8523-67901 | | Copy Processor Board | LJ 9000Lmfp |
| Q1312A | Q1312-60001 | | Copy Connect Card EIO | LJ9000mfp and LJ 9000Lmfp |
| | C8523-60101 | | Copy Connect Cable | LJ9000mfp and LJ 9000Lmfp |
| | Q2679-67901 | | Copy Processor EIO | LJ9040mfp and LJ9050mfp |
| | Q3650-60001 then will roll to Q3650-67901 | | Copy Connect Board Assy | LJ9040mfp and LJ9050mfp |
| | Q3726-60101 | | Copy Connect Cable | LJ9040mfp and LJ9050mfp |
| RG5-5750-210CN | | C8519-69031 | Fuser assembly, 110 V | |
| RG5-5751-210CN | | C8519-69032 | Fuser assembly, 220 V | |
| RG5-5681-030CN | | | Paper input unit (PIU) | |
| RG5-5778-120CN | | C8519-69028 | DC controller | LJ9000mfp and LJ9000Lmfp |
| RG5-7780-000CN | | | DC controller | LJ9040mfp and LJ9050mfp |
| RG5-5728-050CN | | C8519-69015 | High-voltage power supply | |
| RG5-5730-000CN | | C8519-69007 | Low-voltage power supply, 110V | LJ9000mfp and LJ 9000Lmfp |
| RG5-7778-000CN | | | Low-voltage power supply, 110V | LJ9050mfp |
| RG5-5731-000CN | | | Low-voltage power supply, 220V | LJ9000mfp and LJ 9000Lmfp |
| RG5-7779-000CN | | | Low-voltage power supply, 220V | |
| | 5851-1838 | | Control panel assembly | HPLaserJet 9040mfp/9050mfp |
| | RG5-5734-000CN | | Control panel assembly | LJ9000mfp and LJ 9000Lmfp |
| | RB2-6501-000CN (LJ 9000mfp/9 RB2-6500-000CN (LJ 9000mfp/9 Q3726-60105 (LJ 9040mfp/9050 | 000Lmfp) left | Control panel overlay English | See service part number |
| | 5969-9741 (LJ 9000mfp/9000Lm Q3726-60106 (LJ 9040mfp/9050 | fp) mfp) | Control panel overlay French (European) | See service part number |
| | 5969-9472 (LJ 9000mfp/9000Lm Q3726-60107 (LJ 9040mfp/9050 | fp) | Control panel overlay Italian | See service part number |
| - | 5969-9473 (LJ 9000mfp/9000Lm | | Control panel overlay German | See service part |

| | Q3726-60108 (LJ 9040mfp/9050mfp) | | number |
|-------------|---|---------------------------------|------------------|
| | 5969-9474 (LJ 9000mfp/9000Lmfp) | Control panel overlay Spanish | See service part |
| | Q3726-60109 (LJ 9040mfp/9050mfp) | (Castilian) | number |
| | 5969-9475 (LJ 9000mfp/9000Lmfp) | Control panel overlay Dutch | See service part |
| | Q3726-60110 (LJ 9040mfp/9050mfp) | | number |
| | 5969-9476 (LJ 9000mfp/9000Lmfp) | Control panel overlay | See service part |
| | Q3726-60111 (LJ 9040mfp/9050mfp) | Portuguese (Brazilian) | number |
| | 5969-9477 (LJ 9000mfp/9000Lmfp) | Control panel overlay Norwegian | See service part |
| | Q3726-60112 (LJ 9040mfp/9050mfp) | | number |
| | 5969-9478 (LJ 9000mfp/9000Lmfp) | Control panel overlay Swedish | See service part |
| | Q3726-60113 (LJ 9040mfp/9050mfp) | | number |
| | 5969-9479 (LJ 9000mfp/9000Lmfp) | Control panel overlay Finnish | See service part |
| | Q3726-60114 (LJ 9040mfp/9050mfp) | | number |
| | 5969-9480 (LJ 9000mfp/9000Lmfp) | Control panel overlay Danish | See service part |
| | Q3726-60115 (LJ 9040mfp/9050mfp) | | number |
| | Q3726-60116 (LJ 9040mfp/9050mfp) | Control panel overlay Polish | See service part |
| | , | | number |
| | 5969-9482 (LJ 9000mfp/9000Lmfp) | Control panel overlay Russian | See service part |
| | Q3726-60117 (LJ 9040mfp/9050mfp) | | number |
| | Q3726-60118 (LJ 9040mfp/9050mfp) | Control panel overlay Czech | See service part |
| | , | | number |
| | Q3726-60119 (LJ 9040mfp/9050mfp) | Control panel overlay Hungarian | See service part |
| | , | | number |
| | 5969-9489 (LJ 9000mfp/9000Lmfp) | Control panel overlay Chinese, | See service part |
| | Q3726-60120 (LJ 9040mfp/9050mfp) | traditional | number |
| | 5969-9483 (LJ 9000mfp/9000Lmfp) | Control panel overlay Chinese, | See service part |
| | Q3726-60121 (LJ 9040mfp/9050mfp) | simplified | number |
| | Q3726-60122 (LJ 9040mfp/9050mfp) | Control panel overlay Korean | See service part |
| | | | number |
| | Q3726-60123 (LJ 9040mfp/9050mfp) | Control panel overlay Japanese | See service part |
| | | | number |
| | Q3726-60124 (LJ 9040mfp/9050mfp) | Control panel overlay Turkish | See service part |
| | | | number |
| | Q3726-60125 (LJ 9040mfp/9050mfp) | Control panel overlay Hebrew | See service part |
| | | | number |
| | Q3726-60126 (LJ 9040mfp/9050mfp) | Control panel overlay Greek | See service part |
| | | | number |
| | 5969-9492 (LJ 9000mfp/9000Lmfp) | Control panel overlay Arabic | See service part |
| | Q3726-60127 (LJ 9040mfp/9050mfp) | | number |
| | Q3726-60123 (LJ 9040mfp/9050mfp) | Control panel overlay Thai | See service part |
| | | | number |
| | | | |
| | | | |
| Accessories | | | |
| | | | |
| C9147A | C9147-67926 | 16 MB flash firmware DIMM | HPLaserJet |
| | | | 9000mfp/9000Lmfp |
| C7843A | C7843-67901 | 16 MB MEMORY DIMM | HPLaserJet |
| | | | 9000mfp/9000Lmfp |
| C7845A | C7845-67901 | 32 MB DIMM | HPLaserJet |
| | | | 9000mfp/9000Lmfp |
| Q1887A | C7846-67901 | 64 MB DIMM | HPLaserJet |
| | | | 9000mfp/9000Lmfp |
| C9121A | C9121-67901 | 128 MB DIMM | HPLaserJet |
| | | | 9000mfp/9000Lmfp |
| | Q3982-67951 | 32MB DDR DIMM | LJ9040mfp and |
| | | | LJ9050mfp |
| | Q2625-67951 | 64MB DDR DIMM | LJ9040mfp and |
| | | | LJ9050mfp |
| | Q2626-67951 | 128MB DDR DIMM | LJ9040mfp and |
| | · · · · · · · · · · · · · · · · · · · | • | |

| | | | | LJ9050mfp |
|----------------|--------------------------------|-------------------------|--|--------------------------------|
| | Q2627-67951 | | 256MB DDR DIMM | LJ9040mfp and LJ9050mfp |
| Q2628A | Q2628-67951 | | 512MB DDR DIMM | LJ9040mfp and |
| C4103A | C4103-67901 | | HP Fast InfraRed Connect pod | LJ9050mfp HPLaserJet |
| | | | | 9000mfp/9000Lmfp |
| C4293A | | | Font DIMMsimplified Chinese | HPLaserJet 9000mfp/9000Lmfp |
| C4292A | | | Font DIMMtraditional Chinese | HPLaserJet 9000mfp/9000Lmfp |
| J6054B | J6054-61031 | J6054-69031 | Hard disk EIO | HPLaserJet 9000mfp/9000Lmfp |
| J6073A | J6073-61011 new or replacement | J6073-69011 exchange | Hard disk EIO | HPLaserJet 9040mfp/9050mfp |
| | J7948-61001 | one in ge | Internal Hard Disk | LJ9040mfp and LJ9050mfp |
| | 5851-1828 | | Internal HDD Cable | LJ9040mfp and LJ9050mfp |
| J4169A | J4169-61001 | J4169-69001 | HP Jetdirect 610N Fast Ethernet (10/100 Base-TX) EIO | 20000011115 |
| J4135A | J4135-61001 | | HP Jetdirect Connectivity (USB) EIO | |
| Q3701-60002 | | | PCA, Fax Modem Card | LJ9040mfp and LJ9050mfp |
| C8568A | C8568-67902 | | Tray 1 | • |
| C8531A | C8531-67902 | | 2,000-sheet feeder (tray 4) | |
| RG5-6212-300CN | | | 2,000-sheet feeder (tray 4) cassette only | |
| RG5-6225-070CN | | | Vertical transfer assembly | |
| RG5-6228-040CN | | | Paper deck drive assembly | |
| RG5-6208-150CN | | C8531-69013 | Paper pickup assembly | |
| C8084A | | | 3,000 Sheet Stacker | |
| C8085A | | | 3,000-sheet stapler/stacker | |
| C8088B | | | Multifunction finisher | |
| Q5693A | | | 8-bin mailbox | LJ9040mfp and LJ9050mfp |
| C8532A | C8532-67902 | | Duplexer | 20000011111 |
| Documentation | | | | |
| | 5851-1468 | | HP LaserJet Printer Family Print Media Guide | |
| | 5969-6818 | | HP Jetdirect Print Server Administrator's Guide | |
| | 5969-3412 | | HP Jetdirect Print Server Jetadmin Setup Guide | |
| | Q5693-90002 | | Paper Handling Accessories Service Addendum | |
| | C8519-90901 | | HP LaserJet 9000 Start Guide U.S. | |
| | C8519-90902 | | HP LaserJet 9000 Start Guide Americas | |
| | C8519-90903 | | HP LaserJet 9000 Start Guide West Europe | |
| | C8519-90904 | | HP LaserJet 9000 Start Guide North Europe | |
| | C8519-90905 | | HP LaserJet 9000 Start Guide East Europe | |
| | C8519-90906 | | HP LaserJet 9000 Start Guide Asia | |

| www.hp.com/support/lj9000 | HP LaserJet 9000 Use Guide |
|---------------------------|-----------------------------------|
| Q3721-90906 | HP LaserJet 9050 Use Guide |
| Q3721-90931 | HP LaserJet 9000 and 9050 |
| | Series printers Service Guide |
| | |
| C8532-90901 | HP Duplexer Install Guide |
| C8568-90901 | HP Tray 1 Install Guide |
| C8531-90901 | HP 2,000-sheet feeder Install |
| | Guide |
| C8084-90900 | HP Stapler/stacker and Stacker |
| | Install Guide |
| C8088-90903 | HP Multifunction Finisher Install |
| | Guide |
| C8088-90902 | HP Multifunction Finisher Service |
| | Guide |
| C8088-90901 | HP Multifunction Finisher Use |
| | Guide |
| C8519-60102 | HP LaserJet 9000 Series Printer |
| | Software |
| | CD-ROMAmericas |
| C8519-60104 | HP LaserJet 9000 Series Printer |
| | Software |
| | CD-ROMEurope |
| C8519-60105 | HP LaserJet 9000 Series Printer |
| | Software |
| | CD-ROMAsia |
| C8519-60106 | HP LaserJet 9000 Series Printer |
| | Service CD-ROM (English |
| | version) |
| C9152-90901 | PM kit installation guide |

HP CLJ 9500mfp

Table 1. Kits and supplies (continued)

| Item | Product Number | Service part- | Description |
|--------------------------|----------------|--|--|
| | | number | |
| Print cartridge, black | C8550A | C8550-67901 | Replacement print cartridge |
| Print cartridge, cyan | C8551A | C8551-67901 | Replacement print cartridge |
| Print cartridge, yellow | C8552A | C8552-67901 | Replacement print cartridge |
| Print cartridge, magenta | C8553A | C8553-67901 | Replacement print cartridge |
| Image drum, black | C8560A | C8560-67901 | Replacement image drum |
| Image drum, cyan | C8561A | C8561-67901 | Replacement image drum |
| Image drum, yellow | C8562A | C8562-67901 | Replacement image drum |
| Image drum, magenta | C8563A | C8563-67901 | Replacement image drum |
| lmage transfer Kit | C8555A | C8555-67901 | One image transfer belt, one image transfer roller, nine paper rollers, and one ozone filter |
| Image cleaning kit | C8554A | C8554-67901 | One air filter, one transfer cleaner, and one toner collection bottle |
| Fuser kit | | RG5-6098-110CN new C8546-69007 exchange | One fuser assembly |

Table 1. Accessories, exchange parts, and documentation (continued)

| Item | Product number | Service part-number | Description |
|---|--------------------|--|--|
| Staple cartridge for stapler/ stacker | | C8085-60541 | Replacement cartridge |
| Staple cartridge for multifunction finisher | | C8088-60541 | Replacement cartridge |
| Intermediate transfer belt (ITB) assembly | No product number | RG5-6400-030CN new C8546-69002 exchange | Entire assembly |
| Cartridge drive assembly | No product number. | RG5-6188-030CN new C8546-69006 exchange | Entire assembly |
| Power supply 110 V | No product number. | C8546-69003 exchange | PCA assembly |
| Power supply 220 V | No product number. | C8546-69004 exchange | PCA assembly |
| Formatter assembly (LJ 9500) | No product number. | C8546-67911 new C8546-69001 exchange | Does not include memory, firmware, or EIO card |
| Formatter assembly (LJ9500mfp) | Q5915A | Q5915-67901 new Q5915-69001 exchange | Does not include memory, firmware, or EIO card |
| 32 MB compact flash (MFP firmware) | No product number. | Q2635-67909 | Flash firmware, compact flash for the MFP |
| 512 MB RAM DIMM | No product number. | Q2632-67951 | DIMM 512 MB DDR 200-pin SDRAM |
| DC controller | No product number. | C8546-67906 new C8546-69005 exchange | PCA |
| Control Panel | No product number. | 5851-1838 | Control panel display |
| Control panel overlay | No product number. | Q3726-60105 (LJ 9500mfp) | English |
| Control panel overlay | No product number. | Q3726-60106 (LJ 9500mfp) | French (European) |
| Control panel overlay | No product number. | Q3726-60107 (LJ 9500mfp) | Italian |
| Control panel overlay | No product number. | Q3726-60108 (LJ 9500mfp) | German |
| Control panel overlay | No product number. | Q3726-60109 (LJ 9500mfp) | Spanish (Castilian) |
| Control panel overlay | No product number. | Q3726-60110 (LJ 9500mfp) | Dutch |
| Control panel overlay | No product number. | Q3726-60111 (LJ 9500mfp) | Portuguese (Brazilian) |
| Control panel overlay | No product number. | Q3726-60112 (LJ 9500mfp) | Norwegian |
| Control panel overlay | No product number. | Q3726-60113 (LJ 9500mfp) | Swedish |
| Control panel overlay | No product number. | Q3726-60114 (LJ 9500mfp) | Finnish |
| Control panel overlay | No product number. | Q3726-60115 (LJ 9500mfp) | Danish |
| Control panel overlay | No product number. | Q3726-60116 (LJ 9500mfp) | Polish |
| | - | | |

| Control panel overlay | No product number. | Q3726-60117 (LJ 9500mfp) | Russian |
|--|--------------------|---|---|
| Control panel overlay | No product number. | Q3726-60118 (LJ 9500mfp) | Czech |
| Control panel overlay | No product number. | Q3726-60119 (LJ 9500mfp) | Hungarian |
| Control panel overlay | No product number. | Q3726-60120 (LJ 9500mfp) | Chinese, traditional |
| Control panel overlay | No product number. | Q3726-60121 (LJ 9500mfp) | Chinese, simplified |
| Control panel overlay | No product number. | Q3726-60122 (LJ 9500mfp) | Korean |
| Control panel overlay | No product number. | Q3726-60123 (LJ 9500mfp) | Japanese |
| Control panel overlay | No product number. | Q3726-60124 (LJ 9500mfp) | Turkish |
| Control panel overlay | No product number. | Q3726-60125 (LJ 9500mfp) | Hebrew |
| Control panel overlay | No product number. | Q3726-60126 (LJ 9500mfp) | Greek |
| Control panel overlay | No product number. | Q3726-60127 (LJ 9500mfp) | Arabic |
| Control panel overlay | No product number. | Q3726-60123 (LJ 9500mfp) | Thai |
| HP Fast InfaRed Connect Pod | C4103A | C4103-67901 | Wireless printing device |
| Hard disk EIO | J6073A | J6073-69011 (exchange) | 20 GB hard drive |
| | | J6073-61011 (new or replacement) | 20 GB hard drive |
| HP Jetdirect 620 Fast Ethernet (10/100 Base-TX) (LJ 9500mfp) | No product number. | J7934-61001 new J7934-69001 exchange | Ethernet EIO card |
| PCA Fax modem card | No product number. | Q3701-60002 | Fax |
| HP Jetdirect Connectivity (USB) | J4135A | J4135-61001 | USB EIO card |
| 3,000-sheet stacker | C8084A | Not orderable | Finishing device |
| 3,000-sheet stapler/stacker | C8085A | Not orderable | Finishing device |
| Multifunction finisher | C8088A | C8088-60500 new | Finishing device |
| Duplexer | C9674A | C8088-69500 exchange C9674-67901 new | Required for two-sided printing |
| Pedistal (LJ 9500mfp) | No product number. | C9674-69001 exchange C8546-67909 new | Stand with casters. |
| 2,000-sheet side-input feeder tray | No product number. | C8546-69008 exchange Q1891-67901 new | High capacity tray. |
| 4 for the LJ 9500mfp Discharge comb cleaning brush | No product number. | C8549-69001 exchange RB2-7615-000CN | Used to clean the transfer |
| | No product number. | C8546-60104 | cleaner corona wire Required for the LJ 9500mfp. |
| Cable, power jumper | No product number. | C8546-60108 | Fax cable, extension or |
| Cable, fax custom | · | | formatter. |
| Power cord | No product number. | 5181-3530 | United States, Mexico, Brazil, Canada, Taiwan |
| Power cord | No product number. | 8120-6800 | Israel |
| Power cord | No product number. | 8120-6811 | Korea, Turkey, Portugal, Germany, Spain, France, Netherlands, Norway, Sweden, Finland, Italy, Russia, Czech Republic, Hungary, Poland, Jordan, Lebanon, North Africa |
| Power cord | No product number. | 8120-6812 | Greece |
| Power cord | No product number. | 8120-6813 | South Africa |
| Power cord | No product number. | 8120-6814 | Denmark |
| Power cord | No product number. | 8120-6815 | Switzerland |
| Power cord | No product number. | 8120-8706 | United Kingdom, Hong Kong, Singapore, Malaysia |
| Power cord | No product number. | 8120-8707 | China |
| Power cord | No product number. | 8121-0780 | India |
| Copy connect cable (scanner) (LJ 9500mfp) | No product number. | C8549-60105 | 30 inch cable between the scanner and the print engine |
| Copy processor EIO (LJ 9500mfp) | No product number. | Q2679-67901 | EIO copy processor board |
| Copy connect board assembly | No product number. | Q3650-60001 | PCA-LVDS adapter |
| (in the scanner) | • | | (in the scanner) |
| Clamp, copy connect cable | No product number. | 5851-1964 | Cable retainer clamp |
| Phone cord | No product number. | 8121-0811 | United Stares, Canada, Poland, Russia, Spain, Portugal, Greece, France, Mexico, Brazil |
| Phone cord | No product number. | 8120-8911 | Denmark |
| Phone cord | No product number. | 8120-8912 | Germany |
| Phone cord | <u> </u> | 8120-8914 | • |
| Phone cord | No product number. | | Italy Netherlands |
| Phone cord | No product number. | 8120-8915 | |
| Phone cord | No product number. | 8120-8916 | Norway |
| Phone cord | No product number. | 8120-8917 | South Africa |
| Phone cord | No product number. | 8120-8920 | United Kingdom |

| Phone cord | No product number. | 8120-8921 | Hong Kong |
|--|--|---|---|
| Phone cord | No product number. | 8120-8922 | Czech Republic |
| Phone cord | No product number. | 8120-8923 | France |
| Service manual bundle | No product number. | C8549-99001 | Printer, finishing devices and side-input tray 4 |
| Training kit for HP Color LaserJet 9500/9500mfp printer | No product number. | C8546-60109 | CD- based service training materials |
| User guide | Electronic versions ready to print at: http://www.hp.com/support/lj9500 | | Mini-manual that goes inside of the right door of the HP Color LaserJet 9500 series printer |
| HP Color LaserJet 9500 Series Printer and 9500mfp Use guide and User reference guide | Electronic versions re www.hp.com/support/ support/clj9500mfp | ady to print at: lj9500 or www.hp.com/ | Electronic versions of the user guide and the user reference guide. |